Spratlin, "SVAN ENFC-LEGL-GAWright:mlh-11/3/76-x2576 Durst, ARHM-ASUP

≆..

11/4/76 11/4/76

November 3, 1976

Mr. G. Hemminghaus GAF Corporation 9215 Riverview Drive St. Louis, Missouri 63137

Dear Mr. Hemminghaus:

This is to inform you that Mr. William H. Longston, Environmental Protection Agency, (EPA), Region VII, inspected your facility on October 4, 1976, and determined that it is in compliance with EPA Regulation 40 CFR 61.22(c) under the terms of the Section 113 Order dated August 3, 1976.

Acceptance of this determination does not relieve GAF Corporation of any responsibility for continuing compliance with Air Pollution Control Regulations, including proper operation and maintenance of the pollution control equipment. There will be periodic inspections, by both the State and Environmental Protection Agency, to assure continued compliance with regulations.

If you have any questions, please contact me at 816/374-2576.

Sincerely yours,

OTKF 30290599

OUOO

Superfund

4.2

Gale A. Wright, P.E. Legal Branch Enforcement Division

cc: Division of Environmental Quality, Jefferson City, Missouri 65101

xc City of STL

4 4 4	CONCURRENCES							
SYMBOL	EUPC-LEGL	1111			•			
SURNAME }	Haw -	1/1/1/2						
DATE	-11-3-76	W 1/1 /	: .					٠, ٠

ORM 1320-1

File: COLP-ASBESTOS CE, GAF COULS, MO. TEL

# TELEPHONE CONVERSATION RECORD

DATE OF CALL 3/29/77	TIME OF CALL
PPRSON ASKED PORI	PERSON CALLINGI Tack Holloway
OFFICE AND/OR PHONE!	GAF
	New Jersey (201-629-3508)
WESTER New Process Pla	and for St. Lovis City.
DIBOUSSIONI Holloway SA	ed they were adding
a rew process to the	en existing facilityin
St. Cours. They cure	
coment mas a plant	( all info. filed under
NESHAPS). They	re planning to install
an independent proce	ess to minufacture
soly westhere fram	roof pleck intulation.
	be little in the way of
porteculate emissio	
the the shiel dense	
The State, which referred	and it is from and
The City sent him an an suggested he talk to E	08 about any Toderal
	of Mr. Halloway dwas
	I standards that would
apply. As we describe	of the PSD and NSPS
regs. and agreed this	new facility did not
appear to fall within	any of the sertment
source gategories. d	Ald him he should beal agency in the NSR.
deal directly with the	beal agency w.r.t. NSR.
· · · · · · · · · · · · · · · · · · ·	

SERVICE.

### NESHAPS INVESTIGATION

GAF Corporation
Building Products Division
9215 Riverview Drive
St. Louis, Missouri

4280-1008 Coded 11/4/76 ph

A reinspection tour of this facility was made at 3 p.m. on October 4, 1976, by Richard Knapp, City of St. Louis, Division of Air Pollution Control, Department of Public Safety, and William H. Longston, Surveillance and Analysis Division, Environmental Protection Agency. The inspection tour was provided by William Neal, Personnel Manager and Safety Manager, and G. Robert Reed, Plant Engineer.

The original inspection of this facility was made on February 4, 1976. See the report dated February 23, 1976, for process details. Many parts of the process were not in operation at that date and a reinspection was made on June 8, 1976. See the report dated July 17, 1976. This report concluded that the main baghouse system was in violation of the hazardous air pollution regulation [40 CFR 61.22 (c)]. It was recommended that appropriate action consistent with that violation be taken. An order to that effect dated August 3, 1976, was issued.

By a letter, dated August 30, 1976, GAF Corporation informed this agency that compliance would be achieved by September 15, 1976.

This reinspection of the main baghouse was for the purpose of final compliance determination.

## Discussion of Compliance Status

At the time of this inspection both process lines were in full operation, the scrap pulverizer was in operation and the facility could be characterized as "in full operation." No visible emissions could be observed from this operation. It was, therefore, determined that this process was in compliance with 40 CFR 61.22 (c).

## Recommendation

It is recommended that no further action be taken as a result of this inspection and that GAF Corporation be informed of their compliance status.

LONGSTON, Leader, Inspection Unit

SPRATLIN, Chief, Ain Section

Corporate Environmental Engineering Department

rporations or the Environmenta and Alps Road Wayne. New Jersey 0747. Telephone (201) 628-3501

September 13, 1976

U. S. Environmental Protection Agency 1735 Baltimore Street Kansas City, Missouri 64108

Attention Mr. Earl J. Stephenson Director, Enforcement Division

> Reference: GAF Corporation, St. Louis, Mo. Plant Order Dated August 3, 1976 for Compliance with Clean Air Act

#### Gentlemen:

GAF is in compliance with 40 CFR 61.22 (c)(2), as ordered. Replacement of the baghouse filter tubes was completed, and there are no visible emissions from the collector. Compliance will be maintained by means of weekly internal inspections and the prompt repair or replacement of any element in the collector found to be defective.

Very truly yours,

GAF CORPORATION

H. J. Holloway

cc: Missouri Air Conservation Commission Mr. G. G. Hemminghaus

X - Copy to W. Spratlin. 9-16-76

## GAF Corporation

Corporate Environmental Engineering Department 1361 Alps Road Wayne, New Jersey 07470 Telephone (201) 628-3501



August 30, 1976

4280-1008

U. S. Environmental Protection Agency 1735 Baltimore Street Kansas City, Missouri 64108

Attention Mr. Earl J. Stephenson, Director, Enforcement Division

Reference: GAF Corporation, St. Louis, Mo. Plant Order Dated August 3, 1976 for Compliance with Clean Air Act

#### Gentlemen:

GAF will repair the existing baghouse and achieve compliance with 40 CFR 61.22 (c)(2) by September 15, 1976, as ordered.

Attached is a copy of an acknowledgment for the purchase of 720 filter tubes for the collector. According to the manufacturer, the permeability of the fabric does not exceed 20 cu. ft. per minute per square foot.

40% of the collector has already been re-bagged and the remainder of the bags will be replaced as soon as the new ones are received early in September. A quantity will be kept in stock for future replacement.

Additionally, we have purchased a Visolite Leak Detector System from Baghouse Accessories Co. division of Standard Havens, Inc. Used for internal inspections of baghouses, the system is effective in revealing the location of any leaks.

Very truly yours,

GAF CORPORATION

H. J. Holloway

cc: Missouri Air Conservation Commission Mr. G. G. Hemminghaus

xc WA Spratlin-9/3/76

REGIONAL DEFICE

FD-57632 DAF CORP 7215 KIVERVICK OK SAME LO SOLE TO ADDYLOS ST LOUIS MO 63137 8-10-76, URGENTLY NEEDED. SHIP BAL. WK. DESCRIPTION (BRAND) YTITHAUD 726 ėΑ FILTER TUDES FOR WHEELABRATOR COLLECTOR CLUIH 1712-194 5" DIA. X 914" LUNG (LOUP TOP) SALES TAX

F

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

August 3, 1976

Mr. G. Hemminghaus GAF Corporation 9215 Riverview Drive St. Louis, Missouri 63137

Dear Mr. Hemminghaus:

Pursuant to Section 113(a)(3) of the Clean Air Act, as amended (42 U. S. C. 1857c-8), enclosed is an Order issued this date containing a schedule to achieve compliance with the Clean Air Act. Any violation of the terms of this Order would subject GAF Corporation to a civil action for appropriate reflief under Section 113(b). In addition, Section 113(c) provides for criminal penalties for violations of an Order.

If you have any questions, please contact Mr. Henry F. Rompage, Attorney, Division of Enforcement, Environmental Protection Agency, Region VII, Kansas City, Missouri, at 816-374-2576.

Sincerely yours,

Earl J. Stephenson Director Enforcement Division

Enclosure

cc: Mr. Michael T. Marshall

Missouri Air Conservation Commission

bcc: Mr. William F. Johnson, Acting Director, Division of Stationary

Mr. Robert L. Markey, Director, Air and Hazardous Materials Division

Mr. James L. Wilson, Department of Natural Resources

Ms. Patsy Burrell

14. C-12. GL: RFHOMPAGE: ne: 8-3-76: x2576								
	CON	CURRENCES						
STMOOL DENT FERL								
SURNIME & Roombracks & M								
DATE S-3-72	65							
T04 T0514 4544 4			OFFICIAL FILE COPY					